

INSTRUCTION SHEET

Buell
AMERICAN MOTORCYCLES

-J02899

Kit Number 59041-03Y

REV. 6-11-2003

XB CARBON FIBER REAR FENDER

General

This kit fits all 2003 and later XB9R, XB9S, XB9SL, XB12R and XB12S model motorcycles.

NOTES

See the Service Parts illustration for a list of items contained in this kit.

A Service Manual for your model motorcycle is available from your local Buell Dealer.

Installation

The installation procedures for this kit is the same as the original equipment (OE) installation procedures in the Service Manual. Refer to the appropriate Service Manual for the rear fender removal and installation procedures. The OE hardware will be re-used in the kit installation.

WARNING

The rider's safety depends on the correct installation of this kit. **USE THE APPROPRIATE SERVICE MANUAL PROCEDURES.** If the procedure is not within your capabilities or if you do not have the correct tools, have your Harley-Davidson Dealer perform the installation. Improper installation of this kit could lead to an accident and result in death or serious injury.

Part No. 59041-03Y


Date 6/03

Service Parts

Buell
AMERICAN MOTORCYCLES

XB CARBON FIBER REAR FENDER

105695



Item	Description
1	Rear Fender

Part No.
59041-03Y